

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 036

MRICAN - CEPIT



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+004

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,7 M
TYPE PERKERASAN : Aspal

NO. RUAS 036	NAMA RUAS MRICAN - CEPIT	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN 1
-----------------	-----------------------------	-----------------	----------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 036

MRICAN - CEPIT



LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,7 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,7 M
TYPE PERKERASAN : Aspal

NO. RUAS 036	NAMA RUAS MRICAN - CEPIT	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN 2
-----------------	-----------------------------	-----------------	----------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 036

MRICAN - CEPIT



LOKASI : STA 0+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,1 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
036	MRICAN - CEPIT			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 036

MRICAN - CEPIT



LOKASI : STA 0+447

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+500

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
036	MRICAN - CEPIT			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 036

MRICAN - CEPIT



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
036	MRICAN - CEPIT			5