


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 100

Gandu - Potorono



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
100	Gandu - Potorono			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 100

Gandu - Potorono



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
100	Gandu - Potorono			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 100

Gandu - Potorono



LOKASI : STA 0+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+400

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
100	Gandu - Potorono			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 100

Gandu - Potorono



LOKASI : STA 0+500

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+570

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
100	Gandu - Potorono			4