

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Koroulon - Purwobinangun**



LOKASI :               **STA               0+000**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN :       8               M  
TYPE PERKERASAN :       Aspal


LOKASI :               **STA               0+009**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       5.6               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS                | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------------|-----------------|----------------|---------|
| 105      | Koroulon - Purwobinangun |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Koroulon - Purwobinangun**



LOKASI :               **STA               0+100**

KONDISI PERKERASAN :       Baik  
LEBAR PERKERASAN :       5.4               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+200**

KONDISI PERKERASAN :       Baik  
LEBAR PERKERASAN :       5               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS                | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------------|-----------------|----------------|---------|
| 105      | Koroulon - Purwobinangun |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Koroulon - Purwobinangun**



LOKASI :               **STA               0+262**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       5               M  
TYPE PERKERASAN               :       Aspal


LOKASI :               **STA               0+275**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       8.9               M  
TYPE PERKERASAN               :       Aspal

| NO. RUAS | NAMA RUAS                | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------------|-----------------|----------------|---------|
| 105      | Koroulon - Purwobinangun |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Koroulon - Purwobinangun**



LOKASI :               **STA               0+280**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       8.9               M  
TYPE PERKERASAN               :       Aspal

| NO. RUAS | NAMA RUAS                | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------------|-----------------|----------------|---------|
| 105      | Koroulon - Purwobinangun |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Ngemplak - Ngaglik**



LOKASI :           **STA           0+000**

KONDISI PERKERASAN :

LEBAR PERKERASAN :       11           M

TYPE PERKERASAN :       Aspal

LOKASI :           **STA           0+031**

KONDISI PERKERASAN :

LEBAR PERKERASAN :       4.1           M

TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 168      | Ngemplak - Ngaglik |                 |                | 1       |