

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 0+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 8.3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+005**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 0+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 1+041**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+046**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 1+500**

KONDISI PERKERASAN : **Baik**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 2+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+761**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Josari



LOKASI : **STA 2+764**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 8.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 8.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
107	Plumbon - Josari			17