


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 17.7 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+010**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+215**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+220**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+464**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+495**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+754**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+764**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+821**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+825**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+160**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 1+164**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : STA 2+010

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : STA 2+022

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : STA 2+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal



LOKASI : STA 2+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+346**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 2+354**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			22

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			23


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			24

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			25

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 3+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			26

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			27

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			28

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : STA 4+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : STA 4+157

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			29

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayunan - Candi Karang



LOKASI : STA 4+162

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal



LOKASI : STA 4+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
108	Kayunan - Candi Karang			30