

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu
Blembem - Kaliwanglu



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 0+500**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA** **1+100**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+200**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA** **1+300**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+400**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA** **1+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA** **1+571**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 5.3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA** **1+600**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 5.3 M

TYPE PERKERASAN : Aspal



LOKASI : **STA** **1+700**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Kaliwanglu



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+220**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : #REF!



LOKASI : **STA 2+228**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
110	Blembem - Kaliwanglu			14