

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+007**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+586**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+300**

KONDISI PERKERASAN : Sedang


LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+500**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 2+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 3+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 3+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 3+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 3+838**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+992**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			22

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Blembem - Tanen



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
111	Blembem - Tanen			23