

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 1+600**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.6 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+614**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.6 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 1+700**

KONDISI PERKERASAN : **Rusak Ringan**
 LEBAR PERKERASAN : 5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : #REF!



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+600**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 6.3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 2+689**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	#REF!			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 3+200**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 3+400**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 3+500**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 3+600**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 3+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			22

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 4+100**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			23

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA 4+200**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 4+300**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			24

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambangan-Ngepring



LOKASI : **STA** **4+346**

LOKASI :

\

KONDISI PERKERASAN : **Sedang**

KONDISI PERKERASAN

LEBAR PERKERASAN : 7.9 M

LEBAR PERKERASAN : M

TYPE PERKERASAN : Aspal

TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU PKP KAB. SLEMAN	PETUGAS SURVEY	HALAMAN
114	Jambangan-Ngepring			25