

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlacap**



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 33.5 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+020**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 7 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlacap |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlacap**



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 5.4 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlacap |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlacap**



LOKASI :               **STA               0+300**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       5.4               M  
TYPE PERKERASAN               :       Aspal




LOKASI :               **STA               0+400**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       5.4               M  
TYPE PERKERASAN               :       Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlacap |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlacap**



LOKASI :               **STA               0+500**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       5.4               M  
TYPE PERKERASAN               :       Aspal



LOKASI :               **STA               0+600**

KONDISI PERKERASAN               :       Baik  
LEBAR PERKERASAN               :       5.4               M  
TYPE PERKERASAN               :       Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlacap |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlcap**



LOKASI :                **STA                0+700**

KONDISI PERKERASAN                :        Baik  
LEBAR PERKERASAN                :        5.4                M  
TYPE PERKERASAN                :        Aspal



LOKASI :                **STA                0+800**

KONDISI PERKERASAN                :        Sedang  
LEBAR PERKERASAN                :        5.4                M  
TYPE PERKERASAN                :        Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlcap |                 |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlcap**



LOKASI :                **STA                0+900**

KONDISI PERKERASAN                :        Baik  
LEBAR PERKERASAN                :        5.2                M  
TYPE PERKERASAN                :        Aspal



LOKASI :                **STA                1+000**

KONDISI PERKERASAN                :        Sedang  
LEBAR PERKERASAN                :        5.2                M  
TYPE PERKERASAN                :        Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlcap |                 |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlacap**



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlacap |                 |                | 7       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Mulungan-Tlacap**



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6.8 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+310**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 23 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 117      | Mulungan-Tlacap |                 |                | 8       |