

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 10.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+318**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+318**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : STA 1+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.9 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+313

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Randugowang



LOKASI : STA 1+310

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
118	Gondanglegi - Randugowang			9