

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+000**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 13 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 5.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4.7 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+130**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.8 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+134**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+550**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+567**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7.1 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+124**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 1+129**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+313**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 1+317**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan


LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+530**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 8 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mancasan - Kepitu



LOKASI : **STA 1+542**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 22 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+540**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 22 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
123	Mancasan - Kepitu			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngemplak - Ngaglik



LOKASI : **STA 0+000**

KONDISI PERKERASAN :
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+031**

KONDISI PERKERASAN :
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
168	Ngemplak - Ngaglik			1