

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 8.8 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.6 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.1 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+910**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 0+941**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+954**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+036**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			9


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+730**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA** **1+800**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 3.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+858**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 6.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA** **1+863**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+900**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA 2+136**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 8.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+144**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisobo - Krandon



LOKASI : **STA** **2+000**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 15 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
124	Kadisobo - Krandon			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngemplak - Ngaglik



LOKASI : **STA 0+000**

KONDISI PERKERASAN :
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+031**

KONDISI PERKERASAN :
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
168	Ngemplak - Ngaglik			1