

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 19.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 19.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 0+019**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.7 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.8 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 5.3 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan


LEBAR PERKERASAN : 5.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA** **1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA** **1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA** **1+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA** **1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+070**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 2+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+768**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Morangan - Klelen



LOKASI : **STA 2+776**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
127	Morangan - Klelen			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngemplak - Ngaglik



LOKASI : **STA 0+000**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 11 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+031**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
168	Ngemplak - Ngaglik			1