

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 18.7 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+006

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : STA 0+100

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,3 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : STA 0+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : STA 0+460

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+815

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : **STA 0+840**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : **3,4** M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 014

BABADAN - KARANGNONGKO



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
014	BABADAN - KARANGNONGKO			8