

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tunggularum-Tritis



LOKASI : **STA 2+147**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+155**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
141	Tunggularum-Tritis			12