

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 0+000**

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 32 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+035**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 1+022**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+033**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+133**

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 1+200**

KONDISI PERKERASAN : **sedang**
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : **sedang**
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA** **2+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA** **2+100**

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA** **2+200**

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **2+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 2+500**

KONDISI PERKERASAN : sedang

LEBAR PERKERASAN : 5.7 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 2+600**

KONDISI PERKERASAN : sedang

LEBAR PERKERASAN : 5.2 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 2+700**

KONDISI PERKERASAN : sedang

LEBAR PERKERASAN : 5.2 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+100**

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : STA 3+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : STA 3+290

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : STA 3+294

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 8 M
TYPE PERKERASAN : Aspal




LOKASI : STA 3+300

KONDISI PERKERASAN : sedang
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 3+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.2 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 3+500**

KONDISI PERKERASAN : sedang


LEBAR PERKERASAN : 5.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : **STA 3+600**

25

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.6 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			22

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : STA 3+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 3+874

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			23


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngawen-Kenteng



LOKASI : STA 3+884

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 13.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
142	Ngawen-Kenteng			24