

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 16 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 8.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+219**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+231**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+300**

03:01

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+749**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlati-Karanggeneng



LOKASI : **STA 0+770**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 18 M

TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN : M

LEBAR PERKERASAN : M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
147	Mlati-Karanggeneng			7