

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : **STA 0+000 KIRI**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 17.6 M

TYPE PERKERASAN : Aspal

LOKASI : STA 0+000 KANAN

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 17,6 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : **STA 0+050**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4,7 M


TYPE PERKERASAN : Aspal

NO. RUAS 015	NAMA RUAS KARANGLO - BABADAN	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN 2
-----------------	---------------------------------	-----------------	----------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : STA 0+720

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+750

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+900


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 015

KARANGLO - BABADAN



LOKASI : STA 1+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+060

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
015	KARANGLO - BABADAN			8