

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+958**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 0+963**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA** **1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA** **1+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA** **1+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+130**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko - Klaci



LOKASI : **STA 2+140**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 23.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
158	Senuko - Klaci			14