


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 14 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+012**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA** **0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA** **0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : STA 0+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : STA 0+900

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+159**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 1+186**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA** **1+210**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.2 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+300**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA** **1+400**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 4.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+500**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 4.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 1+510**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+524**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 2+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 2+400**

KONDISI PERKERASAN : **Rusak Ringan**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 3+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : STA 3+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			21



LOKASI : STA 3+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : STA 3+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			22



LOKASI : STA 3+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			23



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			23

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci




LOKASI : **STA 4+000**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			24



LOKASI : **STA 4+100**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			24

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundong-Klaci





LOKASI : **STA 4+200**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 4.3 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 4+211**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 17 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
160	Pundong-Klaci			25