


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 29.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+021**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+373**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+378**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+803**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+809**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 1+051**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+056**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			11


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



22 Okt 2025 09:58
7,731722S 110,458307E
Kabupaten Sleman
#Ruas No 17 #STA 1+700
#Survei Kondisi Jalan #DPU Kab. Sleman



22 Okt 2025 10:03
7,731503S 110,457353E
Kabupaten Sleman
#Ruas No 17 #STA 1+800
#Survei Kondisi Jalan #DPU Kab. Sleman

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



22 Okt 2025 10:07
7,731517S 110,457158E
Kabupaten Sleman
#Ruas No 17 #STA 1+836
#Survei Kondisi Jalan #DPU Kab. Sleman



22 Okt 2025 10:10
7,731555S 110,457005E
Kabupaten Sleman
#Ruas No 17 #STA 1+848
#Survei Kondisi Jalan #DPU Kab. Sleman

LOKASI : **STA 1+836**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+848**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			17


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 2+934**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 2+939**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			22

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 3+292**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			23

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 3+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			24

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 3+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			25

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 3+711**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+742**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			26

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			27

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 4+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			28

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 4+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 4+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			29

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 4+355**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 4+363**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			30

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngangkruk - Babadan



LOKASI : **STA 4+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
17	Ngangkruk - Babadan			31