

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 38,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+016**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+765**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 1+184**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+190**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 1+536**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6,3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+553**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			11


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Somokaton - Banyuurip



LOKASI : **STA 1+555**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 15,6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
182	Somokaton - Banyuurip			12