

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bletuk-Kliwonan



LOKASI : **STA 1+482**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.8 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+490**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 15 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
186	Bletuk-Kliwonan			9