

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 17.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+012**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : **4.1** M

TYPE PERKERASAN : **Aspal**



LOKASI : **STA 0+400**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : **4** M

TYPE PERKERASAN : **Aspal**

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA 0+500**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : **4** M

TYPE PERKERASAN : **Aspal**



LOKASI : **STA 0+600**

KONDISI PERKERASAN : **Sedang**


LEBAR PERKERASAN : **4.6** M

TYPE PERKERASAN : **Aspal**

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA** **0+700**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.2 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+800**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA** **0+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+000**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA** **1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA** **1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Senuko-Rawulu



LOKASI : **STA 1+492**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
197	Senuko-Rawulu			9