


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+007**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+224**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+240**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+451**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+464**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+470**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+488**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+627**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 2+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : STA 2+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : STA 2+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : STA 2+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : STA 2+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngaran - Rewulu



LOKASI : **STA 3+115**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 3+124**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 21 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
199	Ngaran - Rewulu			21