

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 20 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+012**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 0+280**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+210**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+360**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 2+180**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			15


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Puluhdadi - Ngentak



LOKASI : **STA 2+440**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12.5 M
TYPE PERKERASAN : Aspal



NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
20	Puluhdadi - Ngentak			16