

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nasri-Blendung



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+106**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
202	Nasri-Blendung			7