

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+005**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 0+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 1+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 1+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 1+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Turgenen Tegal Donon



LOKASI : **STA 2+068**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+076**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
208	Turgenen Tegal Donon			12