

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Patukan



LOKASI : STA 0+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 14,7 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+007

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
214	Tlogo Lor - Patukan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Patukan



LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
214	Tlogo Lor - Patukan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Patukan



LOKASI : **STA** **0+300**

KONDISI PERKERASAN : **Baik**
 LEBAR PERKERASAN : **4,6** M
 TYPE PERKERASAN : Aspal


LOKASI : **STA** **0+400**

KONDISI PERKERASAN : **Baik**
 LEBAR PERKERASAN : **4,6** M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
214	Tlogo Lor - Patukan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Patukan



LOKASI : **STA** **0+500**

KONDISI PERKERASAN : **Baik**
 LEBAR PERKERASAN : **4,5** M
 TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+600**

KONDISI PERKERASAN : **Baik**
 LEBAR PERKERASAN : **4,7** M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
214	Tlogo Lor - Patukan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Patukan



LOKASI : **STA 0+654**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 4.2 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
214	Tlogo Lor - Patukan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Patukan



LOKASI : **STA 0+775**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 5.6 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+789**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 6.8 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
214	Tlogo Lor - Patukan			6