

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Tanah

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 1+022**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 1+121**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+128**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+226**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Diro-Kwayuhan



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+522**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
215	Diro-Kwayuhan			11