

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+009**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+275**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+298**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+367**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+371**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.3 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+572**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pelemgurih-Gamping



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 14.3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+604**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 30.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
220	Pelemgurih-Gamping			7