

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Tlogo Kidul



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 8.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+007**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
221	Tlogo Lor - Tlogo Kidul			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Tlogo Kidul



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
221	Tlogo Lor - Tlogo Kidul			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Tlogo Kidul



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
221	Tlogo Lor - Tlogo Kidul			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Tlogo Kidul



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
221	Tlogo Lor - Tlogo Kidul			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tlogo Lor - Tlogo Kidul



LOKASI : **STA 0+623**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+620**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
221	Tlogo Lor - Tlogo Kidul			5