

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 14 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+015**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.6 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.6 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : **STA 0+662**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : STA 1+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+069

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Marangan - Candi Boko



LOKASI : STA 1+070

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
226	Marangan - Candi Boko			8