


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 8.9 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+006**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 2+011**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+024**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 2+039**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 2+306**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+311**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nangsri Lor - Ngepring



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.4 M
TYPE PERKERASAN : Aspal



NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
228	Nangsri Lor - Ngepring			16