


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA** **0+000**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 7.4 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA** **0+100**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3.8 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA** **0+200**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 3.8 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA** **0+300**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3.8 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA** **0+400**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 3.8 M

TYPE PERKERASAN : Aspal



LOKASI : **STA** **0+500**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 3.8 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA** **0+600**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 3.8 M

TYPE PERKERASAN : Aspal



LOKASI : **STA** **0+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.8 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 0+800**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 3.8 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 4.2 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3.8 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 2+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+153**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Paving



LOKASI : **STA 3+160**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+169**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+196**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+214**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 19 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			21


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngepring-Turgo



LOKASI : **STA 3+687**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+000**

KONDISI PERKERASAN :
LEBAR PERKERASAN : 0 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
229	Ngepring-Turgo			22