

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+004

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : STA 0+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : STA 0+900

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : STA 1+100

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+200


KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 023

DEMANGAN - MRICAN



LOKASI : STA 1+270

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 8,8 M
TYPE PERKERASAN : Aspal

LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
023	DEMANGAN - MRICAN			8