

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+972**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+091**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+515**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nepring-Boyong



LOKASI : **STA 1+525**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 22.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :

LEBAR PERKERASAN : M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS		PETUGAS SURVEY	HALAMAN
230	Nepring-Boyong	DPU Kab. Sleman		11