

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7.1 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.6 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+536**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+709**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+783**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5.5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5,5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 5.9 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Baratan-Kentulan



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+332**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
234	Baratan-Kentulan			14