

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 20.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+018**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan-Blunyah



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+116**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
238	Nandan-Blunyah			12