

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 8.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+212**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+217**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+300**

03:01

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+160**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jangkang-Padon



LOKASI : **STA 1+164**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7.8 M

TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :

LEBAR PERKERASAN : M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
243	Jangkang-Padon			9