

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 1+041**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.9 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+044**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.75 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sombangan-Lahar



LOKASI : **STA 1+208**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+212**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
247	Sombangan-Lahar			9