

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 17 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+007**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+063**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+396**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Beton

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Beton

LOKASI : **STA 0+563**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Moyudan-Goser



LOKASI : **STA 0+750**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+790**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
249	Moyudan-Goser			7