


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nogosari - Brintik



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 19 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+014**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
250	Nogosari - Brintik			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nogosari - Brintik



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
250	Nogosari - Brintik			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nogosari - Brintik



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
250	Nogosari - Brintik			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nogosari - Brintik



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
250	Nogosari - Brintik			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nogosari - Brintik



LOKASI : **STA 0+619**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+625**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 16 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
250	Nogosari - Brintik			5