

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 14.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+014**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			8

FOTO SURVEY KONDISI JALAN TAHUN 2025**RUAS JALAN : Cungkuk - Glagahombo**LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			9

FOTO SURVEY KONDISI JALAN TAHUN 2025**RUAS JALAN : Cungkuk - Glagahombo**LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 2+093**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+098**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			16


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 2+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 3+210**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+218**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+334**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Cungkuk - Glagahombo



LOKASI : **STA 3+345**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 3+250**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
253	Cungkuk - Glagahombo			21