

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sonoharjo - Ngino



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 18 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+014**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
255	Sonoharjo - Ngino			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sonoharjo - Ngino



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
255	Sonoharjo - Ngino			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sonoharjo - Ngino



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
255	Sonoharjo - Ngino			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sonoharjo - Ngino



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
255	Sonoharjo - Ngino			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sonoharjo - Ngino



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
255	Sonoharjo - Ngino			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sonoharjo - Ngino



LOKASI : **STA 0+869**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+876**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
255	Sonoharjo - Ngino			6