

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+014**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.8 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

64

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+658**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+666**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+148**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grejen - Somorai



LOKASI : **STA 1+163**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
256	Grejen - Somorai			9