

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+008**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.7 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.7 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.7 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.7 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA 0+851**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+856**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nandan - Ngelempongsari



LOKASI : **STA** **0+860**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS		PETUGAS SURVEY	HALAMAN
260	Nandan - Ngelempongsari	DPU Kab. Sleman		7