

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 027

BULAKSUMUR - SAMIRONO



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 22.2 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+010


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
027	BULAKSUMUR - SAMIRONO			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 027

BULAKSUMUR - SAMIRONO



LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9,1 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
027	BULAKSUMUR - SAMIRONO			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 027

BULAKSUMUR - SAMIRONO



LOKASI : STA 0+220

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
027	BULAKSUMUR - SAMIRONO			3