

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 0+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+003**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+929**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+083**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 2+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 2+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+572**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 2+584**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			17


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 2+804**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+810**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			18


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA** **2+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal




LOKASI : **STA** **3+000**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			19


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA** **3+100**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA** **3+200**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Plumbon - Mudal



LOKASI : **STA 3+214**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS		PETUGAS SURVEY	HALAMAN
273	Plumbon - Mudal	DPU Kab. Sleman		21