

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 1+806**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+814**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gondanglegi - Banteran



LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
275	Gondanglegi - Banteran			12